

## Loading Card **Mini Lever Control** DSRML1

### Tools required

- Leonardo Mini Lever Dispenser
- Leonardo Roll towel
- Dispenser key



Roll the towel into the wheel and use the lever to feed through.